

NX 8.5

for Engineers and Designers

CADCIM Technologies

*525 St. Andrews Drive
Schererville, IN 46375, USA
(www.cadcim.com)*

Contributing Author

Sham Tickoo

Professor

*Department of Mechanical Engineering Technology
Purdue University Calumet
Hammond, Indiana
USA*

Kishore Goud

CADSoft Technologies



DEDICATION

*To teachers, who make it possible to disseminate knowledge
to enlighten the young and curious minds
of our future generations*

*To students, who are dedicated to learning new technologies
and making the world a better place to live in*

THANKS

*To the faculty and students of the MET department of
Purdue University Calumet for their cooperation*

To Amit Bhatt for technically editing this manuscript

To Rajendra Badola and Kusha Gupta for copy editing this manuscript

Online Training Program Offered by CADCIM Technologies

CADCIM Technologies provides effective and affordable virtual online training on various software packages including Computer Aided Design and Manufacturing (CAD/CAM), computer programming languages, animation, architecture, and GIS. The training is delivered 'live' via Internet at any time, any place, and at any pace to individuals, as well as the students of colleges, universities, and CAD/CAM training centers. The main features of this program are:

Training for Students and Companies in a Classroom Setting

Highly experienced instructors and qualified Engineers at CADCIM Technologies conduct the classes under the guidance of Prof. Sham Tickoo of Purdue University Calumet, USA. This team has authored several textbooks that are rated "one of the best" in their categories and are used in various colleges, universities, and training centers in North America, Europe, and in other parts of the world.

Training for Individuals

CADCIM Technologies with its cost effective and time initiative strives to deliver the training in the comfort of your home or work place, thereby relieving you from the hassles of traveling to training centers.

Training Offered on Software Packages

CADCIM provides basic and advanced training on the following software packages:

CAD/CAM/CAE: CATIA, Pro/ENGINEER Wildfire, Creo Parametric, SolidWorks, Autodesk Inventor, Solid Edge, NX, AutoCAD, AutoCAD LT, Customizing AutoCAD, AutoCAD Electrical, EdgeCAM, and ANSYS

Computer Programming: C++, VB.NET, Oracle, AJAX, and Java

Animation and Styling: Autodesk 3ds Max, 3ds Max Design, Maya, and Alias Design

Architecture and GIS: Autodesk Revit Architecture, AutoCAD Civil 3D, Autodesk Revit Structures, and AutoCAD Map 3D

For more information, please visit the following link:

<http://www.cadcim.com>

Note

If you are a faculty member, you can register by clicking on the following link to access the teaching resources: ***<http://www.cadcim.com/Registration.aspx>***. The student resources are available at ***<http://www.cadcim.com>***. We also provide **Live Virtual Online Training** on various software packages. For more information, write us at ***sales@cadcim.com***.

Table of Contents

Dedication	iii
Preface	xvii

Chapter 1: Introduction to NX 8.5

Introduction to NX 8.5	1-2
System Requirements	1-3
Getting Started with NX	1-4
Important Terms and Definitions	1-6
Understanding the Functions of the Mouse Buttons	1-10
Toolbars	1-11
Hot Keys	1-17
Color Scheme	1-17
Dialog Boxes in NX	1-18
Selecting Objects	1-19
Deselecting Objects	1-19
Selecting Objects Using the QuickPick Dialog Box	1-19
Self-Evaluation Test	1-19

Chapter 2: Drawing Sketches for Solid Models

The Sketch task Environment	2-2
Starting NX 8.5	2-2
Starting a New Document in NX 8.5	2-4
Invoking Different NX Environments	2-7
Creating Three Fixed Datum Planes (XC-YC, YC-ZC, XC-ZC)	2-7
Displaying the WCS (Work Coordinate System)	2-8
Creating Sketches	2-9
Creating Sketches in the Sketch task Environment	2-9
Creating Sketches in the Modeling Environment	2-15
Sketching Tools	2-15
Drawing Sketches Using the Profile Tool	2-15
Using Help Lines to Locate Points	2-19
Drawing Individual Lines	2-19
Drawing Arcs	2-19
Drawing Circles	2-21
Drawing Rectangles	2-22
Placing Points	2-24
Drawing Ellipses or Elliptical Arcs	2-28
Drawing Conics	2-30
Drawing Studio Splines	2-31

Filleting Sketched Entities	2-33
The Drawing Display Tools	2-35
Fitting Entities in the Current Display	2-35
Zooming an Area	2-35
Dynamic Zooming	2-36
Panning Drawings	2-36
Fitting View to Selection	2-37
Restoring the Original Orientation of the Sketching Plane	2-37
Setting Selection Filters in the Sketch task Environment	2-37
Selecting Objects	2-39
Deselecting Objects	2-39
Using Snap Points Options While Sketching	2-39
Deleting Sketched Entities	2-40
Exiting the Sketch task Environment	2-40
Tutorial 1	2-41
Tutorial 2	2-44
Tutorial 3	2-50
Self-Evaluation Test	2-54
Review Questions	2-55
Exercise 1	2-56
Exercise 2	2-56

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches	3-2
Concept of Constrained Sketches	3-2
Under-Constrain	3-2
Fully-Constrain	3-2
Over-Constrain	3-2
Degree of Freedom Arrows	3-3
Dimensioning Sketches	3-4
Locking the Automatically Applied Dimensions of the Sketch	3-4
Applying Horizontal Dimensions	3-5
Applying Vertical Dimensions	3-5
Applying Parallel Dimensions	3-6
Applying Perpendicular Dimensions	3-7
Applying Angular Dimensions	3-8
Applying Diameter Dimensions	3-8
Applying Radius Dimensions	3-9
Applying Perimeter Dimensions	3-10
Applying Dimensions by Using the Inferred Dimensions Tool	3-10
Editing the Dimension Value and Other Parameters	3-11
Animating a Fully-Constrained Sketch	3-12
Measuring the Distance Value between Objects in a Sketch	Enhanced 3-13
Measuring the Distance between Two Objects in a Sketch	3-14
Measuring the Projected Distance between Two Objects	3-15

Measuring the Screen Distance between Two Objects	3-15
Measuring the Length of an Arc or a Line	3-16
Measuring the Angle between Entities	3-16
Measuring the Angle Value Using the By Objects Option	3-16
Measuring the Angle Value Using the By 3 Points Option	3-17
Measuring the Angle Value Using the By Screen Points Option	3-18
Geometric Constraints <i>Enhanced</i>	3-18
Applying Additional Constraints Individually	3-19
Applying Symmetry constraint	3-25
Applying Automatic Constraints to a Sketch	3-25
Controlling Inferred Constraints Settings	3-27
Showing All Constraints in a Sketch	3-28
Showing/Removing Constraints	3-28
Converting a Sketch Entity or Dimension into a Reference Entity or Reference Dimension	3-30
Tutorial 1	3-31
Tutorial 2	3-37
Tutorial 3	3-40
Self-Evaluation Test	3-44
Review Questions	3-44
Exercise 1	3-45
Exercise 2	3-46

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches	4-2
Trimming Sketched Entities	4-2
Extending Sketched Entities	4-3
Creating a Corner between Sketched Entities	4-4
Offsetting Sketched Entities	4-5
Mirroring Sketched Entities	4-7
Creating Linear Sketch Pattern	4-8
Creating Circular Sketch Pattern	4-9
Copying, Moving, and Rotating Sketched Entities	4-10
Transforming Sketched Entities	4-15
Editing Sketched Entities by Dragging	4-19
Exiting the Sketch task Environment	4-20
Changing the View of the Sketch	4-20
Creating Base Features by Extruding	4-20
Extrude Dialog Box Options	4-21
Creating Solid Revolved Bodies	4-28
Hiding Entities	4-33
Showing Hidden Entities	4-34
Hiding All Entities Using a Single Tool	4-34
Rotating the View of a Model in 3D Space	4-35
Setting Display Modes	4-36

Tutorial 1	4-36
Tutorial 2	4-39
Tutorial 3	4-43
Self-Evaluation Test	4-46
Review Questions	4-47
Exercise 1	4-48
Exercise 2	4-48

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes	5-2
Types of Datum Planes	5-3
Creating Three Fixed (Principle) Datum Planes	5-3
Creating Relative Datum Planes	5-3
Creating Datum Coordinate Systems	5-9
Creating Fixed and Relative Datum Axes	5-13
Other Extrusion Options <small>Enhanced</small>	5-17
Specifying the Boolean Operation	5-17
Specifying Other Extrusion Termination Options	5-19
Projecting External Elements	5-21
Tutorial 1	5-23
Tutorial 2	5-28
Tutorial 3	5-32
Self-Evaluation Test	5-36
Review Questions	5-37
Exercise 1	5-38
Exercise 2	5-38
Exercise 3	5-39

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes by Using the Hole Tool	6-2
Creating General Holes	6-3
Creating Drill Size Hole	6-4
Creating Screw Clearance Hole	6-5
Creating Threaded Hole	6-5
Creating Hole Series	6-6
Creating Grooves	6-7
Creating Rectangular Grooves	6-8
Creating Ball End Grooves	6-10
Creating U Grooves	6-11
Creating Slots	6-12
Creating Rectangular Slots	6-12
Creating Ball-End Slots	6-15
Creating U-Slots	6-17
Creating T-Slots	6-19

Creating Dove-Tail Slots	6-20
Creating Chamfers	6-22
Creating a Chamfer Feature Using the Symmetric Method	6-23
Creating a Chamfer Feature Using the Asymmetric Method	6-25
Creating a Chamfer Feature Using the Offset and Angle Method	6-25
Creating an Edge Blend	6-26
Tutorial 1	6-31
Tutorial 2	6-39
Self-Evaluation Test	6-46
Review Questions	6-47
Exercise 1	6-48
Exercise 2	6-48
Exercise 3	6-49

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools	7-2
Pattern Feature Tool <i>Enhanced</i>	7-2
Creating Linear Pattern	7-2
Creating Circular Pattern	7-8
Creating Polygon Pattern	7-11
Creating Spiral Pattern	7-13
Creating a Pattern Along a Curve	7-14
Creating Reference Pattern	7-17
Creating a Fill Pattern	7-17
Mirror Feature Tool <i>Enhanced</i>	7-20
Sweeping Sketches Along the Guide Curves	7-21
Creating Swept Features <i>Enhanced</i>	7-23
Creating Tubes or Cables	7-26
Creating Threads	7-27
Creating Symbolic Threads	7-28
Creating Detailed Threads	7-31
Creating Shell Features	7-32
Shelling the Entire Solid Body	7-33
Tutorial 1	7-34
Tutorial 2	7-37
Tutorial 3	7-40
Tutorial 4	7-45
Self-Evaluation Test	7-51
Review Questions	7-52
Exercise 1	7-53
Exercise 2	7-53

Chapter 8: Editing Features and Advanced Modeling Tools-III

Editing Features	8-2
Editing a Hole Feature	8-2
Editing the Positioning of a Groove Feature	8-2
Editing the Positioning of a Slot Feature	8-3
Editing the Parameters of Features	8-3
Editing the Parameters of Features with Rollback	8-3
Editing Sketches of the Sketch-based Features	8-3
Reordering Features	8-4
Advanced Modeling Tools	8-4
Creating Boss Features	8-4
Creating Pocket Features	8-5
Creating Pad Features	8-9
Creating Drafts	8-12
Tutorial 1	8-15
Tutorial 2	8-19
Tutorial 3	8-27
Self-Evaluation Test	8-34
Review Questions	8-35
Exercise 1	8-36
Exercise 2	8-37
Exercise 3	8-38

Chapter 9: Assembly Modeling-I

The Assembly Environment	9-2
Invoking the Assembly Environment	9-2
Invoking the Assembly Environment Using the New Dialog Box	9-2
Invoking the Assembly Environment in the Current Part File	9-3
Types of Assembly Design Approaches	9-3
Creating Bottom-up Assemblies	9-4
Placing Components in the Assembly Environment	9-4
Changing the Reference Set of a Component	9-7
Applying Assembly Constraints to Components	9-7
Points to Remember while Assembling Components	9-17
Creating a Component Array in an Assembly	9-17
Replacing a Component in an Assembly	9-20
Moving a Component in an Assembly	9-21
Mirroring a Component in an Assembly	9-25
Modifying a Component in the Assembly File	9-28
Tutorial 1	9-29
Tutorial 2	9-42
Self-Evaluation Test	9-55
Review Questions	9-56
Exercise 1	9-56

Exercise 2	9-58
Exercise 3	9-61
Exercise 4	9-64

Chapter 10: Assembly Modeling-II

The Top-down Assembly Design Approach	10-2
Creating Components Using the Top-down Assembly Design Approach	10-2
Creating Subassemblies	10-4
Editing Assembly Constraints	10-5
Modifying the Assembly Constraints	10-5
Checking the Interference between the Components of an Assembly	10-6
Checking Interference Using the Simple Interference Tool	10-6
Checking Interference and Clearance Using the Check Clearance Analysis	10-8
Checking Interference Using the Assembly Clearance Method	10-9
Checking Interference and Clearance, and Analyzing Cross-sections of Components Using the View Section Tool	10-15
Creating Exploded Views of an Assembly	10-20
Exploding Views Automatically	10-21
Exploding Views Manually	10-22
Tutorial 1	10-24
Tutorial 2	10-28
Tutorial 3	10-33
Tutorial 4	10-39
Self-Evaluation Test	10-44
Review Questions	10-45
Exercise 1	10-46

Chapter 11: Surface Modeling

Introduction to Surface Modeling	11-2
Invoking the Shape Studio Environment	11-2
Creating an Extruded Surface	11-3
Creating a Revolved Surface	11-3
Creating a Ruled Surface	11-4
Creating a Surface Using the Through Curves Tool	11-6
Creating a Surface Using the Through Curve Mesh Tool	11-8
Creating a Surface Using the Four Point Surface Tool	11-10
Creating a Swoop Surface	11-10
Creating Planar Surfaces from 2D Sketches and Edges of Solid or Surface	11-12
Creating a Transition Surface Using the Transition Tool	11-13
Creating an N-Sided Surface	11-15
Creating a Silhouette Flange Surface	11-18
Extending a Surface Using the Law Extension Tool <i>Enhanced</i>	11-22
Creating a Surface Offset Using the Offset Surface Tool	11-26
Trimming and Extending a Surface Using the Trim and Extend Tool	11-27
Trimming a Sheet by Using the Trimmed Sheet Tool	11-28
Creating a Surface Using the Studio Surface Tool	11-30
Creating a Surface between Two Walls Using the Styled Blend Tool	11-33

Creating Surfaces Using the Styled Sweep Tool	11-38
Sewing Individual Surfaces into a Single Surface	11-39
Adding Thickness to a Surface	11-40
Adding Drafts <i>Enhanced</i>	11-41
Tutorial 1	11-43
Tutorial 2	11-48
Self-Evaluation Test	11-56
Review Questions	11-56
Exercise 1	11-57
Exercise 2	11-58

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies	12-2
Creating Intersection Curves	12-2
Creating Section Curves	12-3
Creating Extract Curves <i>Enhanced</i>	12-8
Creating Isoparametric Curves	12-10
Projecting Curves	12-12
Advanced Surface Modeling Tools	12-15
Creating Dart Features	12-15
Creating Emboss Body on a Sheet or Solid Body <i>New</i>	12-17
Creating Face Blend Features	12-18
Creating Soft Blend Features	12-23
Creating Bridge Features	12-26
Tutorial 1	12-27
Tutorial 2	12-38
Tutorial 3	12-47
Self-Evaluation Test	12-59
Review Questions	12-59
Exercise 1	12-60
Exercise 2	12-61

Chapter 13: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment	13-2
Invoking the Drafting Environment	13-2
Invoking the Drafting Environment Using the Drawing Template from the New Dialog Box	13-2
Invoking the Drafting Environment in the Current Part File	13-3
Editing the Drawing Sheet Parameters in the Drafting Environment	13-6
Invoking the Drafting Tools	13-6
Types of Drawing Views in NX	13-6
Base View	13-6
Projected View	13-7
Detail View	13-7
Section View	13-7
Auxiliary View	13-7

Half-Section View		13-7
Revolved Section View		13-7
Break-Out Section View		13-7
Broken View		13-7
Generating Drawing Views		13-8
Generating Views Using the View Creation Wizard Tool	<i>Enhanced</i>	13-8
Generating the Base View		13-13
Generating the Orthographic Drawing Views Using the Projected View Tool		13-16
Generating the Detail View Using the Detail View Tool		13-17
Generating Section Views Using the Section View Tool		13-21
Generating the Half Section View Using the Half Section View Tool		13-25
Generating the Revolved Section View		13-26
Generating the Break-Out Section View		13-27
Generating the Broken View		13-28
Manipulating the Drawing Views		13-30
Aligning the Drawing Views Using the Align View Tool	<i>Enhanced</i>	13-30
View Boundary		13-32
Displaying the Model Using the Display Sheet Tool		13-34
Inserting a Drawing Sheet Using the New Sheet Tool		13-34
Modifying the Properties of a Generated Drawing View		13-34
Modifying the Scale Value of the Drawing View		13-34
Adding Dimensions to the Drawing Views		13-36
Retrieving Dimensions from the Model		13-36
Adding Dimensions to the Drawing View		13-37
Generating Exploded Views of an Assembly		13-40
Creating Parts List and Associative Balloons		13-40
Creating a Parts List for an Assembly		13-41
Creating Associative Balloons		13-41
Creating a Tabular Note (Title Block)		13-43
Adding Multiline Text to a Drawing Sheet		13-44
Printing Tools		13-45
Print		13-45
Plot		13-46
Tutorial 1		13-47
Tutorial 2		13-52
Tutorial 3		13-58
Self-Evaluation Test		13-65
Review Questions		13-66
Exercise 1		13-67
Exercise 2		13-68

Chapter 14: Synchronous Modeling

Introduction		14-2
Move Face	<i>Enhanced</i>	14-2
Pull Face		14-5
Offset Region		14-7

Replace Face	14-8
Resize Blend	14-9
Reorder Blend	14-9
Resize Chamfer	14-10
Label Chamfer	14-10
Label Notch Blend	14-11
Resize Face	14-11
Delete Face	14-12
Copy Face	14-14
Cut Face	14-15
Paste Face	14-16
Mirror Face	14-17
Pattern Face	14-17
Make Coplanar	14-18
Make Coaxial	14-19
Make Tangent	14-20
Make Symmetric	14-21
Make Parallel	14-22
Make Perpendicular	14-23
Make Fixed	14-24
Make Offset	14-25
Show Related Face	14-26
Linear Dimension	14-26
Angular Dimension	14-28
Radial Dimension	14-29
Shell Body	14-31
Shell Face	14-32
Change Shell Thickness	14-33
Group Face	14-34
Edit Cross Section in History Free Mode	14-34
Edit Cross Section in History Mode	14-36
Tutorial 1	14-36
Tutorial 2	14-42
Self-Evaluation Test	14-51
Review Questions	14-52
Exercise 1	14-53
Exercise 2	14-53

Chapter 15: Sheet Metal Design

The Sheet Metal Module	15-2
Setting the Sheet Metal Part Properties	15-4
Creating the Base feature	15-7
Adding Flanges to a Sheet Metal Part	15-8
Creating Contour Flanges	15-15

Creating Lofted Flanges	15-16
Adding a Jog to the Sheet	15-17
Bending the Sheet Metal Part	15-18
Unbending the Sheet Metal Part	15-19
Rebending the Sheet Metal Part	15-19
Filleting or Chamfering Corners	15-19
Closing the Corners of a Sheet Metal Part	15-20
Creating Dimples in a Sheet Metal Part	15-24
Creating Louvers in a Sheet Metal Part	15-27
Creating Drawn Cutouts in a Sheet Metal Part	15-28
Creating Beads in a Sheet Metal Part	15-29
Adding Gussets to a Sheet Metal part	15-32
Adding Hems	15-35
Creating a Sheet Metal Part using Solid body	15-39
Converting a Solid Part Into a Sheet Metal Part	15-39
Ripping the Corners of a Solid Part	15-41
Creating the Flat Pattern of a Sheet Metal Part	15-41
Creating the Flat Pattern	15-41
Creating the Flat Solid	15-42
Exporting a Flat Pattern	15-43
Tutorial 1	15-43
Tutorial 2	15-53
Self-Evaluation Test	15-59
Review Questions	15-59
Exercise 1	15-60
Exercise 2	15-62
Index	1